



Technical Service Bulletin

MIL on - misfire DTC stored after cold start

01 07 02 Feb. 8, 2007, 2011719/3. Supersedes Technical Service Bulletin Group 01 number 06-04 dated Mar. 15, 2006 due to updated reference to another TSB.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3	2006	All	2.0L TFSI R4 Engine
A4	2005 – 2006	All	3.2L FSI V6 Engine 2.0L TFSI R4 Engine
A6	2005 – 2006	All	3.2L FSI V6

Condition

Sporadically, after cold start, the engine may run slightly rough for a few seconds and the MIL may illuminate with a DTC for misfire on one cylinder only (**P0301**, **P0302**, **P0303**, **P0304**, **P0305** or **P0306**) stored in ECM data memory. The rough running condition disappears a few seconds after cold start and does not exist with a warm engine.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

- Follow normal Guided Fault Finding Diagnosis.
- If diagnosis results are inconclusive, do not carry out any repair or replace any part.
- If condition persists, contact the Audi Technical Assistance Center for further assistance.



Tip: For 3.2FSI Only: Ensure Technical Service Bulletin 2010890 *Cold engine runs rough or stumbles; warm engine may stall when engaging gear and vehicle is stationary* has been performed.

Warranty



Technical Service Bulletin

This TSB is informational only and not applicable to any Audi warranty.

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.