

Technical Service Bulletin



Luggage Cover is Noisy

68 06 04 Oct. 31, 2006, 2012996/1

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6 Avant	2006	000001 – 177000	

Condition

The luggage cover creaks when driving on poor roads.

Technical Background

At times, the springs under the caps may make noise.

Production Solution

Improved production.
Version 21S.

Service

Remove the caps. Grease the springs and the contact surfaces at the points marked by the arrows in the illustration below.

Technical Service Bulletin



Warranty

When procedure applies to vehicles within the New Vehicle Limited Warranty, use the following:			
Claim Type:	W2		
Part Identifier:	6854		
Damage Code:	6854 20 002 1		
Labor Operations:	6854 19 00	Remove and install net partition	20 TU
	6854 49 99	Modify net partition	20 TU
Diagnostic Time:	No Diagnostic Time Allowed		
Claim Comment:	As per TSB #2012996/1		
All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.			

All part and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Dept. and service manuals for the latest information.

