

Technical Service Bulletin



Net partition noisy

68 06 05 Nov. 16, 2006, 2013328/1

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6 Avant	2006	All	Not Applicable
A6 Avant	2007	000001 – 014160	

Condition

Creaking and cracking noises come from the net partition when driving on poor roads or at load change.

Technical Background

Free play in the mechanism.

Production Solution

Improved production.

Technical Service Bulletin



Service

Replace the net partition parts version **22S** or higher. The parts version is written on the white sticker on the net partition.



Tip: The Parts Department only supplies parts with version **22S** or higher.



Figure 1. You will find a white sticker similar to this on the net partition. In this figure, the parts version is circled in yellow.

Warranty

When procedure applies to vehicles within the New Vehicle Limited Warranty, use the following:			
Claim Type:	W2		
Part Identifier:	6854		
Damage Code:	6854 20 002 2		
Labor Operations:	6854 19 00	Insert Labor Operation Description from ElsaWeb	20 TU
Diagnostic Time:	No Diagnostic Time Allowed		
Claim Comment:	As per TSB #2013328/1		
All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.			

Technical Service Bulletin



Required Parts and Tools

Part Number	Part Description	Quantity
4F9 861 691 A XXX	Net partition	1

All part and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Dept. and service manuals for the latest information.