



HYUNDAI Technical Service Bulletin

Group	BODY (INTERIOR/EXTERIOR)
Number	09-BD-007
Date	JULY, 2009
Model	2010 GENESIS COUPE(BK)

Subject
GENESIS COUPE (BK) DOOR BELT WEATHERSTRIP CHANGE

CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER



DESCRIPTION:

This bulletin provides information on changes in Genesis Coupe (BK) door belt weatherstrips as shown below.




[Changes]

- Lower lip of inside door belt weatherstrip has been cut by 4 mm.
- Lower lip of outside door belt weatherstrip has been cut by 4.5 mm.

Previous		New	
			
Door belt - Inside	82231 - 2M0009P (LH) 82241 - 2M0009P (RH)	Door belt - Inside	82231 - 2M0019P (LH) 82241 - 2M0019P (RH)
Door belt - Outside	82210 - 2M000 (LH) 82220 - 2M000 (RH)	Door belt - Outside	82210 - 2M001 (LH) 82220 - 2M001 (RH)

NOTE: The previous door belt weatherstrips are not available as service parts. When the replacement of a door belt weatherstrip is required, use a new type replacement part.

INTERCHANGEABILITY:



EFFECTIVE VEHICLE INFORMATION:

Model: Genesis Coupe (BK)

Effective vehicle production date: December 2, 2008 ~

Normal warranty applies.