



HYUNDAI Technical Service Bulletin

Group	ENGINE MECHANICAL
Number	09-EM-004
Date	JULY, 2009
Model	2010 GENESIS COUPE

Subject
INTAKE AIR FILTER ELEMENT DIFFERENCES FOR GENESIS COUPE ENGINES

CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

DESCRIPTION:

Genesis Coupe 2.0L and 3.8L engines are equipped with different air intake systems and different air filter elements. The air filter element must only be replaced with the appropriate part number as described in this bulletin.

VEHICLES AFFECTED:

- 2010 model year and later Genesis Coupe equipped with 2.0L TCI engine
- 2010 model year and later Genesis Coupe equipped with 3.8L V6 engine

PARTS INFORMATION:



PART NUMBER	APPLICATION	DESCRIPTION
28113-2M000	Genesis Coupe w/ 2.0L TCI engine	Air Filter Element
28113-2M010	Genesis Coupe w/ 3.8L V6 engine	

NOTE: While the general shape appears similar, the direction of the filtering pleats and the airflow openings of the perimeter body are different for each part number.

